


Whirlpool



Modèle:

AMW 730/NB

AMW 730/NB

Code commercial:

858773001920

858773001920

F093034

KitchenAid

Whirlpool


Hotpoint

Bauknecht

i **INDESIT**

WHR05963

Vue éclatée



4000 107 96336

WHR05963

pièces détachées

Liste de

Repè	Code SAV	De S/N	À S/N	Remplacem	Description	Notice	Code
0221	480120100879 (C00321605)				traverse inf. sur la droite		
0222	480120100881 (C00321606)				traverse inf. sur la gauche		
0470	481068978551 (C00325508)				charniere midi ass. 270 dr		
0471	481068978541 (C00325507)				charniere midi ass. 270 l		
1170	481949878366 (C00318974)			1 x 482000022365 (C00469613)	poignee pour plat crisp		
1300	481010458544 (C00324386)				support interrupteur midi		
1305	480120100677 (C00321555)				spring tension		
1308	481010458550 (C00324387)				disque a cames midi		
1410	481010764878 (C00376576)				porte ass. vbl midi bl grill		
2450	482000004533 (C00331927)				grille de tournebroche		
2460	480120100687 (C00318167)			1 x 480131000084 (C00322871)	plat crisp		
2550	481941879728 (C00333013)			1 x C00629087 (488000629087)	plateau tournant		
2640	481010422374 (C00324258)				plateau tourn. cercle 3 roues		
2641	481010545578 (C00313971)				entraineur central		
3010	481010765101 (C00376577)				panneau de commande wp bl		
3320	481010618599 (C00374880)				bouton d1		

3340	481010618353 (C00374879)		bouton bague d1	
3560	481010704685 (C00376554)	1 x C00704323 (488000704323)	afficheur hwcfg-ui vbl d1 mw g	
4040	481010491930 (C00311846)		magnetron lg 2m226-20gwh	
4060	481067848981 (C00313149)		moteur tt	
4120	481010488906 (C00312371)		transformateur r*h.v 230v/50hz phoenix	n2021c00
4200	481212158161 (C00313217)		condensateur at	
4210	481212208003 (C00316062)		filtre secteur	
4260	481221838323 (C00311329)	1 x 482000006101 (C00311368)	diode at	
4410	480120100527 (C00313445)		ventilateur de refroidissement	
4520	480120100667 (C00313505)		resistance grilloir	
4801	481010726987 (C00376565)		faisceau de cables r2.5 c4/5 r2.5 5- pol	
4838	481010516451 (C00376540)		fiche shuko	
4900	481010714748 (C00376562)		cordon secteur	
5210	481010704745 (C00376556)		platine controle hwcfg-acu loke gr mi	
5570	480120100003 (C00320836)		thermostat 165°c	
5571	481067847931 (C00325487)		thermostat 36fxe24 20202 1130c tod	
5620	481925228125 (C00311937)		fusible t 10 a - 250 v	
6330	480120100814 (C00314456)		interrupteur	
6520	481213418008 (C00314704)		lampe cavite	n2021k00

WHR05963

pièces détachées

Liste de

Repè	Code SAV	De S/N	À S/N	Remplacem	Description	Notice	Code
6560	480120101622 (C00317555)				douille lampe		
6913	481010704004 (C00502002)				sonde temper. magn therm oven12/ania2		
7740	480120100672 (C00312952)				plaque mica		
9220	481953268686 (C00314548)				joint caoutchouc moteur		
999	C00514818				mode démo whp		
999	C00514736 (488000514736)				schema a l'echelle whp		
999	C00379460 (488000379460)				schema de cablage whp		
999	C00351860 (488000351860)				conseils de securite whp		
999	C00773151				donnees techniques whp		
999	C00383609 (488000383609)				code erreur whp		
999	C00514817				configuration et mode test whp		

Notices

n2021c00: Required action when replacing the Transformer

When replacing the Transformer ensure to re-use the anti-vibration Rubber by removing it from the original Transformer
In case you need to order the anti-vibration Rubber the code is 481946248431 (C00586020)



n2021k00: Change from an incandescent lamp to halogen

To meet new legislation , this microwave changed from an incandescent lamp to halogen in September 2021. The two versions can be identified by the industrial code. They are not directly interchangeable as the bulb holder and harness have also been modified, but you can order original components till they are out of stock. Then you must order new lamp assy (pos.6520) and new harness (pos.4804)